


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-97 To (mo./yr.) 1-98
2. DOGM File Number (Mine No): 510371101
3. Mine Name: Bacon Rock Quarry
4. Mineral(s) Mined (or permitted to mine): sandstone
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4, ____ 1/4, ____ 1/4, Section 30, Township 38, Range 24
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: Bedrock Stone Co.
8. Permanent Street Address: 111 E. 100 S. 88-15
City, State, Zip: Blanding, Ut. 84511
Phone: 435-678-3928
9. Company Representative (or designated operator):
Name: Eldon E. Virgil
Title: owner
Business Address: 111 E. 100 S. 88-15
City, State, Zip: Blanding, ut. 84511
Phone: 435-678-3928
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? Approx. 1800 Ton
3. If inactive, what year was the mine last active? N/A

3. How much **additional acreage** was disturbed during the past year? 1/2 acre
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
None - working stone from area that has previously
been stripped.
5. How much acreage was **reclaimed** during the past year? 1/2 acre
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
Regraded to existing contour
Area scarified to prevent erosion
Results looking very positive for plant regrowth
7. What is the **total disturbed acreage** at years end? 3 acres
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Mining to continue by same method
Reclamation approx 3/4 acre


NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Eldon E. Virgil
 Title of Operator: owner
 Signature of Operator: 
 Date: 1-28-98